


Some Engineering Problems of the Panama Canal in Their Relation to Geology and Topography Volume 86



Filesize: 7.73 MB

Reviews

If you need to adding benefit, a must buy book. Better then never, though i am quite late in start reading this one. I am effortlessly could possibly get a satisfaction of reading a created pdf.

(Trevor Von)

SOME ENGINEERING PROBLEMS OF THE PANAMA CANAL IN THEIR RELATION TO GEOLOGY AND TOPOGRAPHY VOLUME 86

[DOWNLOAD PDF](#)

Rarebooksclub.com, United States, 2012. Paperback. Book Condition: New. 246 x 189 mm. Language: English . Brand New Book ***** Print on Demand *****.This historic book may have numerous typos and missing text. Purchasers can download a free scanned copy of the original book (without typos) from the publisher. Not indexed. Not illustrated. 1915 Excerpt: .drain pipes to remove the surface water and the very thin mud from the hydraulic-fill pond or sump. By varying the depth of this pond a greater or lesser amount of clayey material could be drained off. As the work progressed, the great mass of the dam slowly settled and became consolidated, and now seems to be almost as stable as a natural ridge or hill. ROME DETAILS OF LOCK CONSTRUCTION. The locks proper are founded on the bedrock of the Gatun formation, but the guide wall that extends out into Gatun Lake had to be built on an artificial foundation, because the bedrock is here about 150 feet below sea level. This wall is cellular and is built of reinforced concrete. The natural ground underlying it was about 8 feet above sea level. On this a wide fill with flat slope was made up to an elevation of 35 feet. Through this fill piles about 60 feet long and spaced 4 feet apart from center to center were driven and their heads were inclosed in a heavy reinforced concrete slab. On this SLIHK; the wall was constructed. As the work progressed a slow settling took place; however, the completed wall is now practically stable. For the construction of the north guide and flare walls, foundational excavations to depths of about 70 feet below sea level had to be made before bedrock was reached. The material removed was too soft to permit loading with steam shovels...

[Read Some Engineering Problems of the Panama Canal in Their Relation to Geology and Topography Volume 86 Online](#)[Download PDF Some Engineering Problems of the Panama Canal in Their Relation to Geology and Topography Volume 86](#)

Other Kindle Books



The Curse of the Translucent Monster! (in Color): Warning: Not a Kids Story!!

Createspace, United States, 2013. Paperback. Book Condition: New. 203 x 127 mm. Language: English . Brand New Book ***** Print on Demand *****.Have you been searching for a great, horrifying read? Something that will really...

[Save eBook »](#)



Index to the Classified Subject Catalogue of the Buffalo Library; The Whole System Being Adopted from the Classification and Subject Index of Mr. Melvil Dewey, with Some Modifications .

Rarebooksclub.com, United States, 2013. Paperback. Book Condition: New. 246 x 189 mm. Language: English . Brand New Book ***** Print on Demand *****.This historic book may have numerous typos and missing text. Purchasers can usually...

[Save eBook »](#)



The First Epistle of H. N. a Crying-Voyce of the Holye Spirit of Loue. Translated Out of Base-Almayne Into English. (1574)

Eebo Editions, Proquest, United States, 2010. Paperback. Book Condition: New. 246 x 189 mm. Language: English . Brand New Book ***** Print on Demand *****.EARLY HISTORY OF RELIGION. Imagine holding history in your hands. Now...

[Save eBook »](#)



Games with Books : 28 of the Best Childrens Books and How to Use Them to Help Your Child Learn - From Preschool to Third Grade

Book Condition: Brand New. Book Condition: Brand New.

[Save eBook »](#)



Games with Books : Twenty-Eight of the Best Childrens Books and How to Use Them to Help Your Child Learn - from Preschool to Third Grade

Book Condition: Brand New. Book Condition: Brand New.

[Save eBook »](#)